

PARRY SOUND AREA LAKE SUMMARIES

Brought to you compliments of:
Gord Pollock, Broker
Century 21 Granite Properties Ltd Brokerage

33 James Street, Parry Sound, Ontario P2A 1T6 Business: 705-746-2158, Fax: 705-746-4746 Residence: 705-746-4816, Cell: 705-774-0955

Website: www.gordpollock.com Email: gord@gordpollock.com

Rainy Lake (Shawanaga)

Created: November 03 Revised:

Location:

Basin and Terrain Characteristics:

Lake Survey Year: 1974

Surface Area:53.9 hectaresMaximum Depth:4.9 metersMean Depth:2.3 metersPerimeter:5.6 kmIsland shoreline:1.1 kmLittoral Zone:100%Thermal Regime:CoolShoreline Development:1 ResortAccess Points:Road (Public)Water Level:Not RegulatedCrown Land:75% Shoreline

Water Quality:

(Parameters pertain to fisheries habitat only. For information on potability of water or contaminates, contact Min. of Health and Min. of Environment.)

Secchi reading: 1.7 meters

Colour:

Dissolved Oxygen:

Alkalinity: 13.7 – Level 3 Moderately Sensitive (MoE,1989)

pH: 6.6 Total Phosphorus: M.E.I.: 15.1

"Guide to eating fish": No Information

Fisheries:

Game Fish Species: Smallmouth Bass, Largemouth Bass (2003), Northern Pike(2003), Yellow Perch

Other species present: White Sucker (2003), Golden Shiner, Brown Bullhead, Pumpkinseed

Exotic Species:

Stocking Record: 1975 Largemouth Bass 5,000 fry

1972 Smallmouth Bass 5,000 fingerling 1971 Smallmouth Bass 1,000 fingerling 1964 Smallmouth Bass 2,000 fingerling 1958 Smallmouth Bass 1,000 fingerling 1957 Smallmouth Bass 1,000 fingerling 1957 Largemouth Bass 5,000 fry 1956 Smallmouth Bass 30 adult 1956 Smallmouth Bass 500 fingerling

Stress Type:

Use Type: Recreation, Recreational Fishing, Tourism Based Industry

Summary of Fisheries Studies / Reports:

Stantec 2003 **CPR Derailment**, mile 39.4 Parry Sound Division, Ontario. **Aquatic Impact Assessment** of Rainy Lake, 2003

- An impact assessment conducted due to a train derailment that spilled styrene and glycol
 into a wetland upstream of Rainy Lake. A small portion of the products escaped to Rainy
 Lake and a wetland area west of Shebeshekong Road.
- Styrene and Glycol levels in the exposure area of the lake never exceeded Provincial Water Quality Objectives
- Benthic invertebrate assessment showed no sign of impairment
- Fish sampled and tested showed no signs of heath impairment nor was styrene detected in any of the samples
- Recommends no further assessment of aquatic communities is required
- The spill of styrene and glycol had no effect on fish, fish habitat or the beneficial uses of fisheries resource in Rainy Lake and further downstream

Management Prescription:		